

Dalston Cemetery Path

When there was a funeral in St Michael's Church followed by a burial it was becoming dangerous walking along the path to the burial site as the path was uneven and broken up in places by the tree roots. There was also a lot of growth spreading into the path causing more cracks and uneven ground.

The Parish Council first arranged to have the growth killed off. The path was cordoned off whilst the workmen resurfaced the path in July 2019. Below are before, during and after photographs.





